


For Husqvarna Parts Call 606-678-9623 or 606-561-4983



Product Service Bulletin



110998-14

1998-11

Engineering Services

Models Affected:

51,55, 55 Rancher, 254, 257, 261, 262

Serial Numbers: Various

Issue Reported: Throttle trigger pin can fall/vibrate out. Replacement pin does not fit tightly in trigger pin hole.

Action Required: Order part # 531 03 05 84. This is an oversized pin and will fit the trigger pin hole with an interference fit.