


Husqvarna

Product Service Bulletin



040799-04

1999-04

Engineering Services

Models Affected:

335XPT

Serial Numbers: All units updated with the oiler update kit or production units which contain a metal oiler adjustment screw.

Issue Reported: Part numbers needed for new components.

Action Required: Use updated crankcase IPL page below.

Model 335 Revisions

