



SERVICE BULLETIN 114

INFORMATIONAL

ISSUED: March 1989
REVISED: June 1995
SUBJECT: Replacement of 590420A Rewind Starter

In the past when using recoil starter 590420A as the replacement, some engines required pop riveting the replacement starter to the blower housing.

Substitution of the pop rivet can be accomplished in the following manner: order bolt part number 650561 (1/4-20 x 5/8) and nut part number 650852 (1/4-20) through your regular source of supply.

This will require the blower housing to be removed and the old starter mounting holes to be drilled out to 1/4" dimension.

The bolts must be inserted into the blower housing from the inside. The starter is placed on top of the blower housing and the nuts are placed on the bolts to secure it.

