



<p>SERVICE BULLETIN 126</p> <p><b>INFORMATIONAL</b></p>
---

**ISSUED:** June 2000

**SUBJECT:** New Quick Fix Carburetor Kits

**MODELS OR TYPES AFFECTED:** Engines Equipped With Series "7" and VLV (vector) Carburetors

We have developed several, quick service repair kits for the series "7" and VLV style carburetors. These kits should help reduce equipment down time while improving your shop efficiency.

These kits include all internal components typically damaged by improper storage or neglect. To maintain emissions compliance under both EPA and CARB regulations you **MUST** follow the engine model cross-reference listed below. Installation of an improper kit is considered a violation of emission regulations.

These kits can be ordered from your normal Tecumseh source of supply under the following part numbers.

<b>Emissionized Engines</b>	<b>Model</b>	<b>Kit Number</b>
	VLV	730637
	OHV 110-135*	730638
	OHV *135-175	730639

\* **Note:** Model OHV135 with specification numbers ranging from 203500 thru 203599 uses kit number 730639.

<b>Non-Emission Engines</b>	<b>Models</b>	<b>Kit Number</b>
	VLV	730235A
	VLV (Victa model)	730641

The Pre-assembled Kits Include the Following: Fuel bowl, Inlet needle and seat, Float, Main jet, Bowl drain screw, Main nozzle and Bowl Gasket.