



# Service Kit 753-05146

Date: 9/30/2005

Subject: Service Replacement for the  
618-04008 and 618-04008A  
transmissions.

Models Affected: N/A

**Read through and understand these instructions completely before proceeding with repair.**

PURPOSE: This kit replaces the 618-04008 and 618-04008A transmissions which are No-Longer-Available.

**NOTE: Save this Instruction Sheet. Refer to it when ordering replacement parts.**

## Service Kit Contents

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	618-04296A	1	TRANSMISSION: SNOW THROWER: SELF PROPEL
2	746-04256	1	CABLE: DRIVE: CLUTCH: 51.19" LG
3	*	1	THIS INSTRUCTION SHEET


\* - Not Available Separately

It is necessary to replace the existing clutch drive cable when converting to the new 618-04296 transmission.

Service Kit 753-05146

1 of 1

Form No. 769-02005A  
(Revised 4/21/2008)



# Service Kit 753-05146

Date: 9/30/2005

Subject: Service Replacement for the  
618-04008 and 618-04008A  
transmissions.

Models Affected: N/A

**Read through and understand these instructions completely before proceeding with repair.**

PURPOSE: This kit replaces the 618-04008 and 618-04008A transmissions which are No-Longer-Available.

**NOTE: Save this Instruction Sheet. Refer to it when ordering replacement parts.**

## Service Kit Contents

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	618-04296A	1	TRANSMISSION: SNOW THROWER: SELF-PROPELLED
2	746-04256	1	CABLE: DRIVE: CLUTCH: 51.19" LG
3	*	1	THIS INSTRUCTION SHEET

\* - Not Available Separately

It is necessary to replace the existing clutch drive cable when converting to the new 618-04296 transmission.

Service Kit 753-05146

1 of 1

Form No. 769-02005A  
(Revised 4/21/2008)

