For Discount Troy Bilt Parts Call 606-678-9623 or 606-561-4983

		Date:	9/19/2008
For A Growing World."	Service Kit	Subject:	Service Replacement for the 719-04177 Cast Iron Pivot Axle
	753-06019	Models Affected:	N/A
	755-06019		N/A

Read through and understand these instructions completely before proceeding with repair.

PURPOSE: This service kit provides a new pivot axle bar and spacers required to replace the 719-04177 pivot axle bar that is no longer available.

NOTE: These materials are prepared for use by trained technicians who are experienced in the service and repair of equipment of the kind described in this publication, and are not intended for use by untrained or inexperienced individuals. Such individuals should seek the assistance of an authorized service technician or dealer.

NOTE: Save this Instruction Sheet. Refer to it when ordering replacement parts.



FIGURE 1

Service Kit Contents

(See Figure 1)

ITEM NO.	PART NUMBER	QTY	DESCRIPTION	
1	719-04177A	1	AXLE: PIVOT: BAR CAST	
2	748-04068	2	SPACER: .71 ID x 1.25 OD x .56 LG	
	*	1	THIS INSTRUCTION SHEET	

* - Not Available Separately

Service Kit 753-06019

Form No. 769-04405

www.mymowerparts.com