Click Here To Go To Installation Instructions





Date: Sept 11, 2000

Bulletin No: 01-03

RCTIC CAT

Product Line: Snowmobile

Model(s): 2001 Panther 440 - U.S. 2001 Panther 440 ESR - U.S. 2001 Z 440 - U.S. 2001 Z 440 ES - U.S. VIN: Not Applicable

Subject: Jet Needle

Condition: It has been determined that the incorrect jet needle was installed on affected models.

■NOTE: International models are not affected.

- **Solution:** Remove existing Jet Needles 6DH7-4 (p/n 6505-215) and replace with jet needles included in Kit (p/n 0637-203).
 - **Parts:** The appropriate number of Jet Needle Update Kit (p/n 0637-203) will be shipped directly to your dealership. Your dealership Parts Account will be charged and then credited upon receipt of Warranty Claim Form(s) from your dealership.

■ NOTE: Kit (p/n 0637-203) is not available at this date but will be shipped directly to your dealership as soon as available. It will not be necessary to call Arctic Cat as the kits will be shipped to you directly from the factory.

Labor: A labor allowance of 0.5 hr will be paid per affected snowmobile.

A Warranty Claim Form of up to 10 vehicle identification numbers (VIN) will be accepted.

Enter 01-03 in the Failure Code section of the Warranty Claim Form.









Arctic Cat[®] Snowmobile Installation Instructions

Jet Needle Update Kit (p/n 0637-203)

NOTE: Read these installation instructions thoroughly before beginning the installation process. Retain these Installation Instructions for future reference.

Kits includes:		
p/n	QTY.	DESCRIPTION
6505-252	2	Jet Needle 6DH2-3
1653-084	1	Instructions

■ NOTE: Jet Needle Update Kit (p/n 0637-203) is to be used in conjunction with Bulletin 01-03. See Bulletin 01-03 for warranty information.

■NOTE: Refer to the 2001 Arctic Cat Snowmobile Service Manual Volume 1, Section 4 for specific procedures regarding the removing and installing procedures for VM-style carburetor components.





Printed in the U.S.A.

^{®TM}Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701

- 1. Remove the carburetor; then remove the existing jet needle.
- 2. Remove the existing jet needle E-clip; then place the same E-clip in the 3rd jet needle position.

■ NOTE: Make sure the E-clip is moved to the 3rd jet needle position.



