





SERVICE 		8
		B0000019

English 1 (1)

SB, 240R, 245R, 250R, Throttle handle, 2000-08

The rear fixing screw for the throttle handle, which passes through the handlebar and was previously self-tapping, has now been replaced with a full-length bolt and nut. Both halves of the handle have a recess for the nut, so the bolt can be inserted from either side.

As a result of this change both halves of the handle must be replaced at the same time on older machines. The bolt and nut are also required.

New ref. no.	Description	Excl ref. no.	Remarks
502 28 06-11	Throttle handle assy.	502 28 06-01	
502 20 85-08	Half handle, left	502 20 85-01	
502 20 86-09	Half handle, right	502 20 86-01	
503 20 02-35	Bolt		
503 22 65-04	Nut		

240R/245R/250R

compl 502 28 06-11

