





<b>SERVICE</b> 		<b>10</b>
		<b>B0100009</b>

English 1 (2)

## SB, 235 R, Bevel gear, 2001-02

The earlier bevel gear (502 18 50-01 assy.) for the 235R is no longer available as a spare part. Similarly, the gear housing 531 00 20-01 and gearwheel kit 503 84 35-01 for this bevel gear have been discontinued.

In recently manufactured machines the bevel gear, 502 18 50-01, was replaced a couple of years ago by the current bevel gear, 503 75 83-01. This bevel gear has a different type of mounting for the spray guard. This means that customers who have the old guards will not be able to fit them to the current bevel gear.

We have therefore produced a kit, ref. no. 537 03 43-02, which, in addition to the bevel gear, contains two spray guards: one for a trimmer head and the other for a grass blade.

Bevel gear assy. 502 18 50-01, gear housing 531 00 20-01 and gearwheel kit 503 84 35-01 have therefore been replaced by the current bevel gear 503 75 83-01 which includes two spray guards. The article number of this kit is 537 03 43-02.

As for the other parts in the earlier bevel gear, the following applies. (See diagram). Earlier bevel gear is at the top.) All parts marked with a dash are fully interchangeable between bevel gears. The remaining parts are standard parts, such as ball bearings, sealing rings, etc. These are still available as spare parts.

New ref. no.	Description	Excl. ref. no.	Remarks
537 03 43-02	Bevel gear assy with guard	502 18 50-01	
537 03 43-02	Bevel gear assy with guard	531 00 20-01	
537 03 43-02	Bevel gear assy with guard	503 84 35-01	



SERVICE



10

B0100009

English 2(2)

