





SERVICE 		2
		B0200022

English 1 (1)

SB, 345, Cylinder, 2002-02

The bearing seats on the cylinders have been widened to provide additional space for the expansion of the rubber part of the bearing holders. This change means a further reduction in temperature.

Introduced from serial number: 345 020401501

New part no.	Description	Excl. part no.	Remark
503 87 02-76	Cylinder assy.	503 87 02-74	345

