





SERVICE 		4
		B0200077

## SB, 346, 351, Fuel hose, 2002-11

To prevent kinking of the fuel hose the grommet in the carburetor area base has been modified. The part number is unchanged. Parts are fully interchangeable. Carburetor area base is now marked with casting code H.

Introduced from serial number:      346      023300001  
   351      023200001

