





|   |  |          |
|---|--|----------|
| SERVICE<br> |  | 4        |
|   |  | B0200078 |

English 1 (1)

## SB, 340, 345, 350, 346, 353, 357, 359, Carburetor and choke valve, 2002-11

To improve starting characteristics a mechanical latch has been introduced for the choke valve. This has now been introduced on the above models. See bulletins: B0200048, B0200055 and B0200070.

When the choke is used it is mechanically locked in the closed position. After start-up the choke lever must be pushed in. This does not occur automatically as before.

