





SERVICE 		8
		B0300049

English 1 (1)

SB, 334 T, 338 XPT, Heat seal, 2003-09

To prevent the operator's hand from getting too hot a heat seal has been introduced on those versions of 334T and 338XPT, which do not have tube muffler. The seal can also be fitted as a field-fix to all earlier produced top handle saws, the 335XPT, 334T and 338XPT, regardless of the type of muffler.

New part no.	Description	Excl. part no.	Remark
--------------	-------------	----------------	--------

503 84 27-01	Heat seal		
--------------	-----------	--	--

Introduced from serial number:

