



SERVICE 		11
		B0300058

English 1 (1)

SB, 323 HD, 325 HD, 326 HD, 325 HS, 326 HS, Cutter bar, 2003-10

An improved design of cutter bar has been introduced. The new design reduces the risk of cutter bars cracking and breaking.

Our stock of spare parts has been replaced with the new design. The part numbers remain unchanged but the new cutter bars are marked with the following revision letters to aid identification.

New part. no.	Description	Excl. part no.	Remark
537 03 80-01	Cutter bar HS 75 cm		Rev. J
537 03 80-02	Cutter bar HS 99 cm		Rev. J
537 10 70-01	Cutter bar HD 75 cm		Rev. F
537 10 70-02	Cutter bar HD 60 cm		Rev. F

