



<b>Service Bulletin</b>
-----------------------------

<b>B0303013</b>
-----------------

<b>2003-07</b>
----------------

---

**Subject:** Hydro-Gear Hydraulic Pumps.

**Affected Models:** All Husqvarna Hydro Walk and Zero Turn Mowers.

**Service Information:**

We now supply seal kits for Hydro-Gear Hydraulic Pumps used on all of our hydrostatic drive mowing products. To be able to order the correct seal kit, the H-G Pump to be resealed must be identified by its BDP (Bantam Duty Pump) number. This number can be found on a label located on the pump housing.

**Parts Information:**

**BDP -10L** Hydrostatic Pump - Seal Kit Part Number **539 108443**

**BDP -10A** Hydrostatic Pump - Seal Kit Part Number **539 108444**

**BDP21L** Hydrostatic Pump - Seal Kit Part Number **539 108445**

**Important Note:**

See service note N0203018 for Hydro-Gear hydraulic system test information, and information for wheel motor seal kit part numbers.