





SERVICE 		13
		B0400011

English 1 (1)

SB, 340, 345, 346 XP, 350, 353, Clutch puller, 2004-01

In order to fit clutches with modified clutch springs (see bulletin B0400010) the clutch puller tool has been modified as shown in diagram B, see description below.

The puller was last modified in 2002-10, see bulletin B0200071, and this modification is shown in diagram A below.

New part no.	Description	Excl. part no.	Remark
502 54 16-03	Clutch puller	502 54 16-02	

