



<b>SERVICE</b> 		<b>2</b>
		X 86.102-26

**MODEL 281 XP**

NEW PISTON

Piston with 2 steel rings is replaced by a new type of piston which has 1 piston ring of cast iron. At the same time piston class C is excluded.

Reference number for cylinder compl. is changed also.

The two piston types are interchangeable.

<u>New Ref. No.</u>	<u>Denomination</u>	<u>Excluded Ref. No.</u>	<u>Remark</u>
501 91 77-02	Piston compl. A	501 80 10-02	
501 91 77-03	Piston compl. B	501 80 10-03	
	Piston compl. C	501 80 10-04	
501 81 29-02	Cylinder compl.	501 81 29-01	
501 91 79-01	Piston ring	501 80 12-01	remains as a spare part

