


MODEL **238, 44**

### OIL TANK VENTILATION

The tank ventilation, which consists of a sinter plug assembled in a roll pin, is excluded from our production.

In exchange, a new compl. tank ventilation will be introduced, which has a cotter pin mounted in a pin (see illustr. ).

A repair kit is available for already produced saws. It contains a roll pin and a cotter pin. The kit is assembled instead of the sinter plug (see illustr.).



The change was introduced from serial number:

238 G	6120909
238	6080480
44	6143222