

MODELS }
MODELES }

266/268/281/298

NEW CLUTCH SPRING

In order to improve the life of the spring, the heat treatment is changed and to simplify the spare parts inventory, the same clutch spring is introduced on the models 266, 268, 281 and 298.

<u>New Ref. No.</u>	<u>Description</u>	<u>Excluded Ref. No.</u>	<u>Remark</u>
503 56 04-01	Clutch spring	501 40 34-02	266
		501 91 98-01	268,281
		501 20 87-01	298
501 77 85-02	Clutch centre compl.	501 77 85-01	266,268
501 67 52-03	Clutch centre compl.	501 67 52-02	281,298

The new clutch spring has a pink colour marking.

NOUVEAU RESSORT D'EMBRAYAGE

Ce ressort a été amélioré au point de vue longévité par un traitement thermique modifié. Pour simplifier la mise en stock nous avons introduit le même ressort d'embrayage pour les modèles 266,268,281 et 298.

<u>Nouvelle réf.</u>	<u>Désignation</u>	<u>Ancienne réf.</u>	<u>Notes</u>
5035604-01	Ressort d'embrayage	5014034-02	266
		5019198-01	268,281
		5012087-01	298
5017785-02	Centre d'embrayage compl.	5017785-01	266,268
5016752-03	Centre d'embrayage compl.	5016752-02	281,298

Le nouveau ressort 5035604-01 est marqué d'une couleur rose.

