





<p>SERVICE</p> 		<p>8</p> <hr/> <p>X 88.112-96</p>
--	--	--

MODEL } **22 RL/25 RL**
 MODÈLE }

Experience from the field shows that the throttle cable does not have satisfactory fit to the throttle trigger on the RL models. In some cases the throttle cable can slip off the throttle trigger and prevent that full throttle is achieved. In order to remedy this, we have made an adapter available.

Ref. No. 502 18 88-01.

Assembly hints

- * Loosen the carburettor cover
- * Screw in the adjustment screw for the throttle cable
- * Loosen the screw which holds the throttle trigger and remove the trigger from the handle
- * Mount the adapter on the throttle trigger. See illustration.
- * Then put the throttle cable housing in the adapter
- * Mount (back) in reverse order and adjust the idle speed

Nous avons appris que le câble de commande des gaz ne convient pas à la commande d'accélérateur des modèles RL. Il arrive en effet que le câble soit mal engagé dans la poignée, réduisant la course du volet des gaz, ce qui se traduit par un manque de puissance. Nous présentons un adaptateur qui élimine ce problème.

Node ref. 5021888-01.

Conseils pour le montage:

- * Dévisser le carter du carburateur
- * Visser la vis de réglage du câble de commande des gaz
- Desserrer la vis de maintien de la commande des gaz et déposer cette dernière de la poignée
- Monter l'adaptateur sur la commande des gaz, voir figure.
- Engager ensuite la gaine du câble de commande des gaz dans l'adaptateur.
- Remonter dans l'ordre inverse, régler le ralenti.

