





SERVICE 		<b>2</b>
		X 90.112-26

## MODEL 281/288

### New cooling air conductor

In order to improve the cooling of the cylinder, the exhaust gasket will be replaced with a cooling air conductor.

New Ref. no.	Description	Excluded Ref. no.
503 51 25-01	Cooling air conductor	501 81 60-02•

\*Remains as a spare part

The change is introduced from serial number:

281-0380112

288-0380079

