

**5**

X 95.005-26

Husqvarna lawn mowers with vibration isolating handle coating

The vibration isolating handle coating can now be replaced instead of changing the entire upper handle.

Assembly is preceded by dipping the handle and coating in warm soapy water.

Allow the coating to remain in the soapy water for 5 minutes before fitting.

When the handle coating has been fitted in the right position the handle should be allowed to dry for 48 hours.

The handle should be hung up from the screw holes to prevent the coating from being flattened.

New Ref. No. Description

516 87 84-09 Handle coating

Excl. Ref. No.

Remarks