



Model 225H

Blade unit

A number of modifications have been introduced to increase the rigidness of the blade unit. The thickness of the material in the blade guard 503 76 98 has been increased and hardened.

The spacer plate 503 78 73 has been excluded.

The thickness of the material in the support plate 503 76 97 has been increased and hardened.

The reference number for the complete blade unit has been changed, other numbers remain as before.

New Ref. No.	Description	Excl. Ref. No.
503 79 38-03	Blade unit compl. H60	503 79 38-01
503 79 38-04	Blade unit compl. H75	503 79 38-02

Due to the increase in the thickness of the blade unit the fixing screws in the gear housing will be replaced. This is a temporary measure and we will soon return to using the original screws.

New Ref. No.	Description	Temporarily replaces
503 20 34-19	Screw MCHSSO M5x19	503 20 02-20
724 13 28-55	Screw M5x14	503 20 02-16

*compl 503 79 38-03 (H 60)
 **compl 503 79 38-04 (H 75)

