

## Model 250PS

### New top section

A new, lighter top section has now been introduced for the shaft lengths 5 and 6 metres. The following applies to older models fitted with aluminium top sections:

When replacing the attachment 502 40 47-02 with the ball-joint compl. 502 42 83-03 the sleeve on the shaft top section 502 42 30-04 must be cut off.

When replacing the shaft top section 502 42 30-04 with shaft top section 502 42 20-02 the attachment 502 40 47-02 must also be replaced with the ball-joint compl. 502 42 83-03.

These components together are cheaper than just the shaft top section 502 42 30-04.

New Ref. No.	Description	Excl. Ref. No.	Remark
502 42 83-03	Ball-joint compl.	502 40 47-02	
502 42 57-01	Socket half	-	
502 42 59-01	Locking nut	-	
502 42 54-01	Ball half	-	
502 42 80-01	Pin top section	-	
503 21 06-25	Screw STC6SF 5.5x25	502 40 93-01	R
503 21 06-22	Screw STC6SF 5.5x22	503 20 02-20	R
729 52 57-75	Screw K35x12 WN 1442	-	
502 42 20-02	Shaft top section	502 42 30-04	

R = Remains as a spare part

