





SERVICE 		2 B9900024
--	--	-----------------------------

English 1 (1)

SB, 340, 345, Cylinder, 1999-06

We are changing over to M6 screws in the production of cylinder joints. To facilitate servicing, four M6 screws will be enclosed with each cylinder supplied as a spare part.

The cylinders are fully interchangeable.

The M6 screws must be tightened to a torque of 12 Nm.

New ref. no.	Description	Excl. ref. no.	Remarks
503 87 00-75	Cylinder assy.	503 87 00-71	H340
503 87 02-75	Cylinder assy.	503 87 02-71	H345
503 20 05-32	Screw M6		

Introduced from serial number:	340	992500501
	345	992500001

