


MODEL: 335XPT

SUBJECT: Sporadic Oiling

It has been reported that some saws in cooler climates tend to oil sporadic. If you should experience this, install oil cap, Part Number **503 82 95-01**.

Should you still experience sporadic oil flow refer to Service Note: *335XPT, Chain Lubrication, 050997-10, 1997-05*.



Part Number
503 82 95-01

Description
Filler Cap Gray