



# Service Bulletin

**Date:** December 18, 2002

**Product Line:** Snowmobile

**Bulletin No:** 2003-1-25

**Subject:** Steering Adjusting Block Caps (Lower)  
Upgrade

**Affected Models / VIN:**

2003 Firecat 500

VIN Range: 4UF03SNW13T170427 - 4UF03SNW63T172402

2003 Firecat 700

VIN Range: 4UF03SNW83T172403 - 4UF03SNW33T177525

■ **NOTE:** For identification purposes, it is necessary to refer to only the last six digits of the vehicle identification number.

■ **NOTE:** In our continuing effort to produce quality products, Arctic Cat is dedicated to upgrading a product that does not meet our specification standards and/or expectations. Arctic Cat is issuing Service Bulletin 2003-1-25 to ensure that our products meet our specification standards and expectations.

**Condition:** It has been determined that the existing steering adjusting block caps (lower) on the affected models do not meet Arctic Cat standards and must be replaced.

**Solution:** Install Steering Adjusting Block Cap Update Kit (p/n 0637-247).

**Parts:** Firecat Update Kit(s) (p/n 0637-247) are being sent directly to your dealership to start upgrading approximately 50 % of the affected snowmobiles at your dealership. Your dealership Parts Account will be charged and then credited upon receipt of a Warranty Claim Request form.

Additional kits should be ordered through normal parts-ordering channels.

**Warranty:** A labor allowance of 0.2 hr will be paid per affected snowmobile.

Only one vehicle identification number (VIN) can be entered per claim. Do not submit a group claim.

CatTracker Claim: Enter BS200325 in the Complaint section.

Manual Claim: Enter 0325 in the Complaint section.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



1202