

Service Advisory

Product Line: Snowmobile **Date:** January 31, 2003

Advisory No: SAS315 Subject: Ski Pressure Adjustment

Affected Models:

All 2003 Bearcat Wide Track Models

Recently, Arctic Cat has received inquiries about ski pressure adjustment on the 2003 Bearcat Wide Track snowmobiles. More specifically, inquiries about when to adjust ski pressure and how to adjust ski pressure have been received.

First of all, the amount of ski pressure desired is a matter of preference and depends upon an operator's individual style of riding. For example, if a snowmobile is being operated on an uphill climb, is pulling heavy loads, or is carrying a passenger, more ski pressure may be advisable.

If riding style includes any of the above and more ski pressure is desired, ski pressure can be increased by simply tightening the front arm adjusters until approximately 38.1 mm (1 1/2 in.) of thread is exposed behind each adjuster nut.

■ NOTE: Since riding preferences vary, the amount of front arm adjustment may vary. Adjust the front arm adjuster according to preference.

For more specific information regarding ski pressure adjustment, refer to the 2003 Snowmobile Operator's Manual (p/n 2256-590).

Please notify your customers concerning this issue.

Thank you for your cooperation in this matter.

Sincerely,

Product Service Department Arctic Cat Inc.







