





SERVICE 		2 B0001007
--	--	-----------------------------

English 1 (1)

SB, 345, Cylinder with Smart Start, 2000-03

Following requests we have now introduced the Smart Start feature on the model 345. This requires a new cylinder assembly and new cover plates that are slightly narrower than the previous version.

NOTE! The new cover plates, ref. no. 503 92 60-02, are NOT interchangeable with the previous version, -01, because of the change in dimensions. The new cylinder requires the new cover plates, while the old cylinder requires the old cover plates. This is to prevent damage to the rubber-lined bearing holder.

New ref. no.	Description	Excl. ref. no.	Remarks
503 87 02-74	Cylinder assy.	503 87 02-75	
503 92 60-02	Cover plate	503 92 60-01	*
503 66 54-01	Decompression valve		incl. in model 350
503 55 22-01	Plug		incl. in model 350
503 20 05-32	Screw M6x32		4 pcs.

* still available as spare part

With effect from serial number: 345 000601101

