





SERVICE 		8
		B0001009

English 1 (1)

## SB, 235R, 240L,RJ, 240RBD, 232L, 232R, 232RD, 232RJ, Cylinder cover, 2000-03

When the air purge was introduced a new hole was made in the crankcase for the pump bulb. The earlier cylinder cover without a hole has been replaced with the new one with a hole. A cover plug has been developed for the new cylinder cover so that it can be used on older machines without a air purge.

The cylinder cover and cover plate are supplied together.

New ref. no.	Description	Excl ref. no.	Remarks
537 13 02-01	Cylinder cover	502 19 88-02	incl. cover plate
537 12 75-01	Cover plug		

