





SERVICE 		5
		B0000034

English 1 (1)

SB, 346XP, 351, 350, 345, 340, Air filter, 2000-11

A new air filter has been introduced to prevent the development of excessive play in the filter.

Brought into production serial no:	H351G	20003600001
	H345	20003701501
	H350	20003604562

New ref. no.	Description	Excl. ref. no	Remarks
537 02 40-01	Air filter	503 85 53-01	
537 02 40-02	Air filter	503 85 53-02	
537 02 40-03	Air filter	503 85 53-03	

