

SB, 227, 232, 235, 240, Bevel gear, 2001-03

The fit between the gear housing and the blade shaft bearing has been improved to prevent grease from leaking out between them. A new ball bearing with a better seal has also been introduced.

The new ball bearings have a brown seal in place of the previous black one.

New ref. no.	Description	Excl. ref. no.	Remarks
503 25 23-01	Ball bearing	738 22 01-19	225, 227, 232, 240
503 25 21-01	Ball bearing	738 22 02-19	235

Brought into production from: 01.10 = 503 25 23-01
 00.44 = 503 25 21-01

