



SERVICE 		6
		B0100029

Replaces B0100021
English 1(1)

SB, 340, 345, 350, 351, 346 XP, Starter 2001-05

The starter has been modified to improve performance and has also got a new part number. The starters are fully interchangeable. Component parts are not interchangeable.

Introduced into production from serial number:	340	010604201
	345	010602851
	350	010702451
	351	010500001
	346XP	010700001

New part number	Description	Old part number	Remarks
537 10 47-01	Starter complete	503 88 76-01	
537 09 25-01	Pulley	503 87 63-01	*
537 09 31-01	Spring	503 85 99-01	*

* remains as a spare part

