



SERVICE 		4 B0200054
--	--	-----------------------------

English 1 (2)

SB, 357 XP, 359, Carburettors, Carburettor heating, 2002-06

Revised carburettors have a choke locking function and different levers. The paper gasket has been replaced with a rubber gasket. Special carburettors have been added for models with carburettor heating.

New part no.	Description	Excl. part no.	Remark
503 28 18-15	*Carburettor HDA 198	503 28 16-15 HDA 174	
503 28 18-16	*Carburettor HDA 199 EPA	503 28 16-16 HDA 175 EPA	
503 28 18-09	Carburettor HDA 190 Heated		
503 28 18-10	Carburettor HDA 191 Heated EPA		
537 15 79-01	Choke shaft		
537 15 80-01	Choke lever		
537 15 81-01	Spring		
537 15 82-01	Lever, start throttle		
537 04 50-01	Cover		
501 46 84-01	Spring		
501 46 85-01	Ball		
501 66 69-01	Gasket, rubber	503 80 06-01 Gasket, paper	

Introduced from serial number: *357 022301201
 *359 022100336


Models 359 XPG and 359 G with carburettor heating are fitted with a special carburettor. The differences between the two types of carburettor are that the new one has no filter compensation parts and that cover 503 17 63-01 has a ventilation hole.

CAUTION!

Carburettors with filter compensation cannot be used on chain saws with carburettor heating.



SERVICE



4

B0200054

English 2 (2)

