



SERVICE 		6
		B0300006

English 1 (1)

SB, 340, 345, 350, 346, 353, 357, 359, Starter, 2003-02

Additional ribs have been added to the starter to prevent long chips of wood from being sucked into it.

Introduced from serial number:	340	030505401
	345	030402201
	350	030506301
	346	030500001
	353	030500001
	357	024901428
	359	025001387

New part no.	Description	Excl. part. no.	Remark
537 10 47-02	Starter assy.	537 10 47-01	340, 345, 350, 346, 353
503 93 06-02	Starter assy.	503 93 06-01	357, 359

