





SERVICE 		8
		B0300007

English 1 (1)

SB, 346, 353, Handle bar, 2003-01

The handle has been strengthened in the vicinity of the handle heating switch.

Introduced into from serial number: 346 024900701
353 024900800

New part no.	Description	Excl. part no.	Remark
503 90 93-03	Front handle assy.	503 90 93-02	

