



X 86.105-26


MODEL 44

## IGNITION SYSTEM, IIDA-CIRCUIT

The following improvements have been made:

- A. The air conductor has been equipped with a plastic stop, which defines the lida-circuit in a firm position.
- <u>B.</u> The lida-circuit will be assembled with a lock washer. This gives a better grounding of the lida-circuit.

These measures give the saw an increased reliability.



 $A \ from \ serial \ number \ 6040670$ 

B from serial number 5351301