



X 87,116-26

266 MODEL

CARBURETTOR SUPPORT

Filter holder compl. 504 35 86-10 has received a support for crankcase attachment.

Addition:

725 52 91-56

Screw M4 x 12

503 23 00-01

Washer 4.2 x 9

In order to mount screw and washer on saws of older design, a hole in the crankcase with thread M4 should be drilled. Use drill ø 3.3 and thread tap M4. Use the mounted filter holder as a template. On saws which have no ridge in the crankcase, a washer should also be placed between the support and the crankcase.

The change is introduced from serial number: 266 XP 7051407

> 266 XPG 6491713

