

CORRECTIONS ON THE SPARE PARTS LIST: 10 62 138-98 22R, RL/25R, RL

<u>Square</u>	<u>New Ref. No.</u>	<u>Description</u>	<u>Excluded Ref. No.</u>
C	502 16 99-01	Screw	503 21 83-19 (incorrect no.)
	502 18 51-01	Screw	503 21 83-17 (incorrect no.)
F	503 23 50-08	Spark plug	502 16 64-01
G	503 25 31-01	Needle bearing	502 16 97-01
L	502 18 51-01	Screw	503 21 83-17 (incorrect no.)
M	502 16 99-01	Screw	503 21 83-19 (incorrect no.)
N	503 28 14-02	Carburettor compl.	503 28 14-01
	502 18 21-01	Jet	502 18 46-01

H A special gasket is introduced for the models 22R RL with standard silencer. Ref. No. 502 18 80-01. See illustration.

