

MODEL 22/25

TECHNICAL UPDATING

Models 22 R, 24 R, 25 R to 1987,24 H

It has been requested from the field that the rubber to the primer (x in the illustration) should be introduced as a spare part.

We now have this part available. Ref. No. 502 19 27-01.



Models 22 R, 25 R - 1987-version

Bigger heat shield

A bigger heat shield has been developed in order to reduce the radiation heat from the fuel tank. The new heat shield, which seals better, is available in two designs, as follows:

Model	Ref. No.	Description
22 R 25 R	502 18 86-01 502 18 87-01	Heat shield Heat shield
20 K	502 10 07-01	ficat sinclu

NOTE! The heat shield only fits the 1987-models of 22 R/25 R.

Please turn over

www.mymowerparts.com

For Husqvarna Parts Call 606-678-9623 or 606-561-4983

Model 22 RL/25 RL

Experience from the field shows that the throttle cable does not have satisfactory fit to the throttle trigger on the RL models. In some cases the throttle cable can slip off the throttle trigger and prevent that full throttle is achieved. In order to remedy this, we have made an adapter available.

Ref. No. 502 18 88-01.

Assembly hints

- Loosen the carburetor cover
- Screw in the adjustment screw for the throttle cable
- Loosen the screw which holds the throttle trigger and remove the trigger from the handle
- Mount the adapter on the throttle trigger. See illustration.
- Then put the throttle cable housing in the adapter
- · Mount (back) in reverse order and adjust the idle speed

