

## Model 225/232/235

### Filler cap (Temporary)

We have noticed some leaking problem with the existing cap, especially on loophandle version, and when storing the machine (hanging).

There is now a duckvalve type cap available.

The cap also let pressure out from tank at pressure build up situations.

New ref.no.	Description	Excl. ref.no.	Remark
503 82 95-01	Tankcap	502 08 83-02	Grey
503 82 95-03	Tankcap	502 08 83-03	Green

