

SB, 252RX, 250R, Rubber bellows, 1999-11

The rubber bellows for the throttle cable has been modified to provide a better seal against water.

A lip has been moulded into the inside of the bellows where it fits onto the air filter holder. The lip locates in the slot in the cable holder to prevent water penetrating through the slot from below. See fig. 1.

To make it easier to locate the lip in the slot when fitting the bellows there is a thin ridge on the outside of the bellows that marks the position of the lip on the inside. See diagram 2.

The reference number remains unchanged – 537 01 70-01.

