



**Service  
Note**



**N0203020**

**2002-09**

---

**Subject:** Kohler 26 hp "EFI" Engine Equipped Mowers

**Effected Model Numbers:** All ZTH7226KOA (968999175) & ZTH6126KOA (968999188) Models

---

**Service Information:**

With the extremely high ambient temperatures experienced this summer, the electronic fuel injected Kohler engines have shown a tendency to "vapor lock." Following extensive testing, it has been determined that moving the high pressure fuel components to a cooler environment on the mower greatly reduces the possibility of vapor locking.

The following kit has been released that will move the EFI high pressure fuel components. The kit includes new hoses, hose clamps, a special hose clamp tool, and other miscellaneous items including an illustrated instruction sheet.

With the installation of this kit, other attempts at resolving the vapor locking concern, i.e.; heat shields, etc. should be removed.

**Parts Information:**

**539107828** - Fuel Kit, EFI Engine

**Warranty Information:**

Normal warranty policy applies. One and a half (1.50) hours labor will be authorized for kit installation.