


For Husqvarna Parts Call 606-678-9623 or 606-561-4983



MODEL : 335 XPT

SUBJECT: Reference to part # 503 82 95-01

The oil cap part # 503 82 95-01 used in Service Note 053097-11, 1997-05 is no longer available. The cap that has replaced it is 503 82 80-02 and will not work on the 335 as an oil cap.

You must use Part Number 501 56 45-04 as the vented oil cap.

Remember the 503 82 95-01 is No Longer Available and the cap 503 82 80-02 will not work.