

Read through and understand these instructions completely before proceeding with repair.

PURPOSE: This service kit provides weight distribution support brackets for the 700 Series Lawn Tractors using the OEM-190-180 Rear Bagger Attachment. These brackets replace the 2 hole brackets 783-04137A and 783-04132A that may be supplied with the bagger attachment.

NOTE: These materials are prepared for use by trained technicians who are experienced in the service and repair of equipment of the kind described in this publication, and are not intended for use by untrained or inexperienced individuals. Such individuals should seek the assistance of an authorized service technician or dealer.

NOTE: Save this Instruction Sheet. Refer to it when ordering replacement parts.




FIGURE 1

Service Kit Contents	ITEM	PART	QTY	DESCRIPTION
(See Figure 1)	NO.	NUMBER		
	1	710-1260A	8	SCREW:TT: 5/16"-18 x .750":HXINDWSH
* - Not Available Separately	2	710-3005	2	SCREW:HHCS:3/8"-16 x 1.25":GR5:STD
	3	711-0310	2	PIN:CLEVIS: .50" DIA. x 1.18" LG
	4	712-04065	2	NUT:FLANGELOCK:3/8"-16:GRF:NYLON
	5	714-0145	2	PIN:COTTER:INTERNAL: .092" x 1.64" LG
	6	738-04058	2	SPACER:SHOULDER: .38" x 1.0" x .70"
	7	783-04919	1	BRACKET:MOUNTING: LH/RR
	8	783-04968	1	BRACKET:MOUNTING:RH/RR
	9	*	1	THIS INSTRUCTION SHEET

Service Kit 753-06148

Form No. 769-04943

www.mymowerparts.com