

MTD Engine Warranty Labor Repair Time Supplement
March 1, 2006

| Carburetor System | Time |
|-------------------------------|-------------|
| Air Filter Assembly/Kit | .25 |
| Carburetor Assembly Replace** | .75 |
| Carburetor Rebuild-Major** | 1.25 |
| Carburetor Rebuild-Minor** | 1.0 |
| Fuel Line Kit | .30 |
| Fuel Tank | .30 |

| Starter Assembly | |
|-------------------------|-----|
| Recoil Starter Assembly | .25 |
| Stop Switch and Brake | .80 |

| Ignition System | |
|------------------------|-----|
| Ignition Module | .25 |
| Spark Plug | .10 |
| Flywheel: see Key | |

| Engine | |
|------------------------------|------|
| Oil Drain Plug Assembly | .08 |
| Dipstick Assembly | .16 |
| PCV kit (mesh, disc, gasket) | .75 |
| PVC Tube | .25 |
| Flywheel Key | .50 |
| Flywheel Shroud | .50 |
| Cylinder Head Complete* | 1.0 |
| Governor Return Spring | .20 |
| Gasket Kit Complete* | 2.0 |
| Gasket Kit External* | 1.0 |
| Muffler | .30 |
| Muffler Gasket/Heat Shield | .30 |
| Push Rod Kit* | .50 |
| Valve Kit* | 1.25 |
| Engine Replacement | .80 |

Troubleshooting Time is included with each replacement.

*Major Engine failures that are considered warrantable, it is not required to disassemble engine.

**Check carburetor failures for stale/degraded fuel and debris prior to replacement.

Starters are not repaired under warranty. Replace only as an assembly.

Short block repairs are not to be used for warranty repairs.
Use a Complete Engine Replacement for Major Warranty Repairs