



<b>SERVICE</b> 		<b>1</b>
		X 85.100-96

For a better co-ordination of the different languages for service bulletins we have now started on a new number series.  
The previous bulletin has number X 84.051-96

MODEL }  
MODÈLE } **238**

### REPAIR KIT (SUPPORT – CLUTCH COVER)

The support post, on the crankcase, for the chainbrake (clutch cover), sometimes shows heavy wear,

Therefore, we have made a repair kit available.

The kit contains:     1 support angle  
                          1 screw  
                          1 washer

Reference number: 503 16 18-01

When assembling the repair kit, file off the bottom portion of the post. Then assemble the kit in the right position over the AV-element.

