



MODEL

HUSQVARNA 50**CHAIN GUIDE PLATE**

In order to reduce the risk of leakage between the oil groove on the chain guide plate and the recess on the bar, the lower part of the oil groove is moved up and the hole is reduced, according to the marking (*).

The same reference number as before.

