

Royal 43S/SE

If the lawn mower is difficult to move backwards or forwards, this can be because of the distance between the illustrated axles being too big. This means the gearwheel bottoms on the gear track. To rectify the fault, the wheel axles are realigned until an axle distance of 71,0 mm is obtained. (Measured on the outsides of the axles.)

The lock washer 514 91 08-00 is used when refitting the wheels.

