



|   |          |
|---|----------|
|  | 120596-1 |
|   | 1996-12  |

**MODEL: 371 XP**

**SUBJECT: Cylinder Base Gasket Part #503 64 37-01**

It has been reported that the cylinder gasket has been sucked into the crankcase in some areas around the country. This has been corrected by changing the base gasket to one that has more surface area as pointed out in the gasket below.



In some cases you can still use the old gasket along with a thin coat of gas and oil impervious RTV silicone to insure that it seals. The previous gasket is pictured below.

